

DRUMMOND & ETHERIDGE

30/1/20

JCB 418S

3939hrs

Basic mechanical appraisal as per Skylarc.

Machine is generally in tidy condition however the following issues have been identified for any potential buyer.

The engine starts and runs at low RPM without problem however at higher RPM the engine will at times miss and surge indicating a potential fuel issue. This is under investigation.

It is understood that oil samples of both the front and rear diffs were carried out some time ago. The results indicated issues that would require repair but these were never carried out. I have not drained the oil however the machine operated in the yard without any noticeable noises.

Battery terminals are corroded and require cleaning.

Several lights are not operational including beacon. Likely to only require bulbs.

Window washers not operating.

Grease line fitting to spear end of lift ram is broken.

Self-leveling/crowd linkages at cab end of boom have some wear in bushes.

Machine has play at lower pivot point. This is not seen as excessive but will need to be monitored.

Two front and one rear Fender extensions have damage at outer edges.

Damage to RH front wheel rim outer bead. Not excessive but there is some denting.

Handbrake is ineffective

RR tire has 60% tread, RF tire has 30% and a split though one layer of side wall, LF tire like new, LR tire 30% with some de-lamination.